Edmonton Forklift Operator Certification

Edmonton Forklift Operator Certification - Forklift operator certification is normally needed for employees working in industrial, warehouse or construction setting to ensure the safe use of forklifts. Workplace training has to follow a method of testing and education. There are two common ways to get forklift operator training and acquire certification. Individuals can look for training by themselves or through the company wherein the person is employed.

Local safety organizations need most companies that own and utilize forklifts to make sure that all forklift operators are certified. Companies can face penalties and fines for failing to properly train all forklift operators.

Forklift training and certification which is offered by the employers is normally facilitated by an on-site manager. Programs would usually consist of safety measures, instruction on the forklift and its components and the right operation of the forklift. Testing would be performed in order to assess knowledge. A test of performance takes place at the end of the program. If successful, the trainee would be given a certification card.

The alternative method to employer offered training is to enroll in a program at a forklift certification training school. These schools will provide instruction on several types of forklifts. Safety procedures are a major focus of the training. A driving test and written test must be successfully completed before a forklift certification card is issued. The lift truck certification designation could be transferred to work performed on a lift truck with whoever employer, which makes it convenient for people searching for a forklift operator job.

Incorrect lift truck operation can result in serious injury to the operator, other employees or company property. To avoid accidents, supervisors must make certain that all relevant personnel get certified. Forklift certification is normally valid for two or three years, after which re-certification is needed.